HMI EX70H(A)/EX100HA PLC - Analog input x1

Category:	Accessories - mobile
Manufacturer:	Mobilator

Product from the Archive - production finished

Single PLC input for standard analog signals for EX70H, EX70HA and EX100HA operator panel.

DESCRIPTION:

Analog inputs are used to measure temperature, pressure, flow, rotation, etc. These measurements are made by converting, for example, the temperature to an analog signal, eg 0 ... 10 V. These signals are processed in the controller. The PLC and the controller respond according to a predetermined algorithm by controlling the corresponding digital or analog outputs.